

## Water Slide, Slide Tower Bridge Maintenance and Repairs at Indoor Pool

			<i>Company</i>	<i>Company</i>
			<i>Bazan Painting Co.</i>	<i>Safe Slide Restoration</i>
			1273 N. Price Road Saint Louis, MO 63132	PO Box 186 Fredericktown, MO 63645
<i>Item</i>	<i>QTY</i>	<i>Description</i>		
#1	L.S.	Repair all structural repair in ride path including spider cracks & raised edges	\$2,000.00	\$1,700.00
#2	L.S.	Re-caulk all seams as needed	\$3,000.00	\$1,700.00
#3	L.S.	Lay non-skid at start tub	\$450.00	\$1,700.00
#4	L.S.	Clean, polish & wax entire interior of slide	\$2,180.00	\$1,700.00
#5		Bridge Repair		
a.	L.S.	Remove all stair treads	\$400.00	\$2,600.00
b.	L.S.	Grind out all rusted areas	\$708.00	\$2,000.00
c.	L.S.	Apply rust transformer or rust inhibitor	\$300.00	\$2,000.00
d.	L.S.	Prime coat all bare steel with PPG Armerlock 2 or comparable	\$700.00	\$2,700.00
e.	L.S.	Paint entire structure with PPG PSX 700 Navy Blue or comparable, 1 extra can of paint to be left	\$2,312.00	\$5,100.00
f.	L.S.	Replace one broken stair tread	\$780.00	\$1,500.00
#6	L.S.	Slide & Stair Structure Repair		
a.	L.S.	Remove all stair treads	\$1,200.00	\$4,000.00
b.	L.S.	Grind out all rusted areas	\$1,100.00	\$4,000.00
c.	L.S.	Apply rust transformer and rust inhibitor	\$1,000.00	\$4,000.00
d.	L.S.	Grind surrounding area of water pipes	\$200.00	\$4,000.00
e.	L.S.	Prime coat all bare steel with PPG Armerlock 2 or comparable	\$1,200.00	\$14,350.00
f.	L.S.	Paint entire structure with PPG PSX 700 Navy Blue or comparable, 1 extra can of paint to be left	\$7,864.00	\$14,350.00
		<b>TOTAL</b>	<b>\$25,394.00</b>	<b>\$67,400.00</b>
#7		Federal Apprenticeship Policy	100%	Not Indicated
		Cash Discount	0%	0%