

Various Equipment Parts for The Golf Club of Florissant

Item No.	Qty	Description	Company		Company	
			Unit	Total	Unit	Total
			O'Reilly Auto Parts 8405 N. Lindbergh Florissant, MO 63031		Turfwerks 11200 St. Charles Rock Rd. Bridgeton, MO 63044	
Ventrec Mower						
1	3	10 Micron Hydraulic Filter, 21.0124	\$10.24	\$30.72		
2	3	25 Micron Hydraulic Filter, 21.0122	\$8.17	\$24.51		
3	5	01 Hydraulic Fluid Gallon, 15.0032	\$14.99	\$74.95		
4	3	Engine Oil Filter, 13.0268				
5	3	1 Engine Oil - 10W30, 15.0037	\$22.99	\$68.97		
6	3	Air Filter, Safety 13.0060	\$27.46	\$82.38		
7	3	Air - Filter, Primary 13.0061	\$22.55	\$67.65		
8	3	Fuel Filter, 13.0053	\$10.88	\$32.64		
9	1	PTO Belt, 81.b038	\$20.85	\$20.85		
10	1	Wheel Assembly Deck, 53.0140				
11	1	Dust Cap, 93.0080				
12	1	Deck Belt, 81.B045				
13	1	Belt, 81.AA096	\$15.78	\$15.78		
14	1	Belt, 81.BB078				
15	1	Deck Spring, 41.0084				
16	1	Right Hand Blade, 79.0079				
17	1	Left Hand Blade, 79.0080				
18	1	Left Hand Blade Bolt, 91.0814-8L				
19	1	Right Hand Blade Bolt, 91.0814-8				
20	1	Anti-Scalp Roller, 70.8152	\$19.99	\$19.99		
21	1	Rear Roller, 80.0383				
Total				\$438.44		\$0.00
John Deere 520 Front Loader Tractor						
1	2	Push Pull Cables, AW27921				
2	1	Oil Filter, T19044	\$8.41	\$16.82		
3	1	Hydraulic Filter, RE45964				
4	1	Fuel Filter, RE60021	\$26.09	\$26.09		
Total				\$42.91		\$0.00
Jacobsen Eclipse 322 Greensmower						
1	4	Rocker Switch, 4130132			\$13.58	\$54.32
2	1	1 Joystick, I Axis, 1004290			\$283.60	\$283.60
3	1	Switch mow, 4174684			\$33.56	\$33.56
4	2	Tire, 18 x 10.5, 420822				
5	1	Lord steer my unit, 4146530			\$1,292.01	\$1,292.01
6	1	Chain # 40, 81 Pitches, 4166403			\$37.86	\$37.86
7	1	Motor, power steering, 4140026			19.83.29	\$1,983.29
8	1	Lift Actuator, 4165944			\$628.14	\$628.14
9	1	Motor Reel, 4261470			\$1,091.59	\$1,091.59

Various Equipment Parts for The Golf Club of Florissant

10	12	Bedknife, 5033479			\$60.54	\$726.48
11	2	Reel 15 Blade (22"), 4225505			\$633.79	\$1,267.58
12	6	(22") Rear Roller, 1004990			\$141.89	\$851.34
13	6	(22") Grooved Segmented Roller, 69673				
14	6	(22") Solid tubed Steel Roller, (light) 68530			\$306.75	\$1,840.50
15	4	Engine Oil Filter, 5000440	\$6.54	\$26.16	\$15.18	\$60.72
16	4	Engine Air Filter, 5000441	\$17.61	\$70.44	\$21.10	\$84.40
17	3	Fuel Filter, 5000436	\$3.74	\$11.22	\$11.76	\$35.28
18	4	Reel Motor Coupler, 4247911			\$6.21	\$24.84
19	4	Woodruff Key, 463029			\$2.33	\$9.32
20	4	Roller Adjustment Knob, 3005692			\$25.43	\$101.72
21	4	Trunnion Internal, 4256227			\$12.89	\$51.56
22	5	Compression Spring, 4256231			\$7.63	\$38.15
23	12	Half Inch Belleville Washer, 400051				
24	12	Trunnion Half, 4256232			\$10.77	\$129.24
25	12	5/16 Belleville Washer, 400065			\$0.44	\$5.28
26	25	Cotter Pin, 5/64 by 3/4, 460008			\$1.51	\$37.75
27	6	Zerk Bolt, 1002224			\$10.50	\$21.00
Total					\$107.82	\$10,689.53

John Deere 2653B Trim Mower

1	3	Engine Oil Filter, M806418	\$8.02	\$24.06		
2	3	Hydraulic Oil Filter, AM102723	\$33.26	\$99.78		
3	3	Hydraulic Oil Filter-Spin On, LVU14258	\$34.26	\$102.78		
4	3	Fuel Filter Element, M801101	\$10.59	\$31.77		
5	1	Belt-Fan (S/N020119), R81271				
6	1	Belt Fan (S/N 020120), LVU11659				
7	1	Battery (DRY), TY25876	\$118.09	\$118.09		
8	1	Key, AR51481				
9	1	Key-Padded, AM12504				
10	1	Ignition Switch, TCA22740				
11	1	Temp Switch, CH15516				
12	1	Oil Pressure Switch, M809526				
13	1	Operator Presence Switch, AET10449				
14	1	Thermostat, M811895				
15	1	Regulator, AM126304				
16	1	Alternator, AM879144	\$118.09	\$118.09		
17	1	Control Module Kit, TCA16744				
18	1	Kit-Brake Pads(S/N-050000), AMT442				
19	1	Lever Body Kit – R/H(S/N-050000), AMT442				
20	1	Lever Body Kit – L/H(S/N-050000), AMT444				
21	1	Disk Brake Hub (S/N 050001), TCU28817				
22	1	Disk Brake Hub (S/N 050000), M122378				
23	1	Wheel Motor -Front, AET11112				
24	1	Wheel Motor -Rear, TCA17053				
25	1	Gasket Kit – Front/Rear Wheel Motor, AZ45116				

Various Equipment Parts for The Golf Club of Florissant

26	1	Wheel Motor -Front, AET11112				
27	1	Wheel Motor -Rear, TCA17053				
28	1	Gasket Kit – Front/Rear Wheel Motor, AZ45116				
29	1	Seal Kit- Hydraulic Solenoid, AT224862				
30	1	Reel Pump Repair Kit, AMT2679				
31	1	Air Filter- Primary, M113621	\$22.07	\$22.07		
32	1	Air Filter- Secondary, M123378	\$17.42	\$17.42		
33	5	Plus-50 II 15W-40 Engine Oil- 1 qt, TY26674	\$4.99	\$24.95		
34	5	Torq-Gard Supreme 15W-40 Engine Oil, TY26799	\$4.99	\$24.95		
35	6	JD Hy-Gard Hydraulic Oil (J2OC) - 1 Gal, TY6354	\$18.99	\$113.94		
36	3	John Deere Special Purpose and Turf Cutting Unit Grease (14oz), TY25083				
37	6	John Deere Multi – Purpose SD Polyurea Grease (14oz), TY6341	\$4.99	\$29.94		
38	3	Bed knife – Standard – 30 in, MT11973				
39	12	Screw – M8 – (12), 19M7573				
40	3	Bearing Cone, JD8933	\$12.41	\$37.23		
41	3	Bearing Cup, JD8253	\$5.72	\$17.16		
42	5	Seal, TCU25266				
43	3	Roller-Smooth – 30 in, AMT2976				
Total				\$782.23		\$0.00

Jacobsen LF 570 4WD

1	1	Wheelmotor, 4209440			\$2,664.60	\$2,664.60
2	1	Tire (26.sv14-12), 4236060			\$356.09	\$356.09
3	2	Engine Oil Filter, 557759	\$10.45	\$20.90	\$14.73	\$29.46
4	1	Motor – front traction, 4209440			\$2,664.60	\$2,664.60
5	2	Charge Filter Element, 2811255	\$65.09	\$130.18	\$49.10	\$98.20
6	2	Filter - Hydraulic, 557772	\$16.73	\$33.46	\$22.78	\$45.56
7	7	Bedknife - Heavy, 503460			\$79.46	\$556.22
8	1	Reel 9-Blade, 2810471			\$624.35	\$624.35
9	2	Bearing Cup and Cone, 5002477			\$50.39	\$100.78
10	2	Scal, 3006030			\$8.61	\$17.22
11	13	Screws, 3009138			\$50.56	\$50.56
12	2	Zerk Bolts, 1002226			\$13.63	\$27.26
13	7	Rear Roller, 1002446			\$230.81	\$1,615.67
14	1	Fuel Filter, 2500809	\$11.12	\$11.12	\$10.58	\$10.58
15	2	Air Cleaner Element, 5000919	\$27.46	\$54.92	\$37.23	\$74.46
16	2	Return Filter, 557772	\$16.37	\$32.74	\$22.78	\$45.56
17	4	Coupler, 4166860			\$58.61	\$234.44
18	3	Greens care 68 Hydraulic Oil, 5003103			\$262.98	\$788.94
19	20	Spring, Urethane, 3010470			\$8.03	\$160.60
Total				\$283.32		\$10,165.15

Toro 3150 Tee Mower

1	6	Bed Knives, 94-6392				
2	12	Flange Bushing, 52-2890				

Various Equipment Parts for The Golf Club of Florissant

3	10	Bumper,94-4548				
4	6	Bushing, 3-1506				
5	3	Pull Frame Roller, 133-2337				
6	3	Roller Shaft, 21-8470				
7	4	Oil Filter, 107-7817	\$11.10	\$44.40		
8	6	Bed Knives, 93-4263				
9	1	Backlap Kit, 04498				
10	1	Regulator, 691185	\$87.99	\$87.99		
11	1	Brake Shoe, 70-9840				
12	2	Fuel Filter, 94-2690	\$4.91	\$9.82		
13	2	Air Filter, BS394018S	\$17.61	\$35.22		
14	2	Hydraulic Filter, 107-9531	\$11.32	\$22.64		
15	3	Filter AC Cartridge, BS394018S	\$17.61	\$52.83		
16	3	Reel-DPA (21), 8 BLD 127-2193				
17	3	DPA Reel Seal Kit 106-6937				
18	6	Bearing, 93-2489	\$40.10	\$240.60		
19	3	Washer-Wave, 105-5700				
20	39	Screw-Bed Knife, 119-4151				
21	3	Bed Knife-Low Cut, 93-4264				
22	3	Rear Full Roller Asm (ST EEL), 120-9595				
23	3	Narrow Wiehle Roller Asm, 115-7360				
Total				\$493.50		\$0.00

Smithco Sandpro

1	1	Tire 22 x 11 – 10 Knobby, 45-021-01			\$188.90	\$188.90
2	1	Hub, 80-019			\$92.55	\$92.55
3	1	Safety Filter, SMI42-834-03			\$15.79	\$15.79
4	1	Air Primary Filter, SMI42-076-03			\$49.92	\$49.92
5	1	Belt, 42-359			\$47.74	\$47.74
6	1	Idler Pulley, 42-358			\$76.37	\$76.37
7	1	Disc Brake, 60-563			\$89.97	\$89.97
8	1	Disc Brake – inside, 60-564			\$90.24	\$90.24
9	1	Hydraulic rear lift, 43-150			\$328.87	\$328.87
10	5	Finishing Blades, 13-443			\$58.87	\$294.35
11	3	Groomer Blades, 42-171			\$34.75	\$104.25
12	1	Hydraulic oil filter SMI23-031			\$34.92	\$34.92
13	3	Engine Oil filter 492932			\$9.65	\$28.95
14	12	Spring Tines SMI42-122			\$15.55	\$186.60
15	1	Seat switch SMI14-292			\$21.27	\$21.27
Total					\$0.00	\$1,650.69

Smithco Tour Ultra Greens Roller 7590

1	2	Pre-Air Filter Element, 272490S	\$3.99	\$7.98	\$4.10	\$8.20
2	2	Air Filter, 394018S	\$17.61	\$35.22	\$13.50	\$26.30
3	1	Fuel Filter Part One, 691035	\$6.09	\$18.27	\$5.60	\$5.60
4	1	Fuel Filter Part Two, 808116S	\$5.52	\$22.08	\$8.95	\$8.95

Various Equipment Parts for The Golf Club of Florissant

5	2	Engine Oil Filter, 491056	\$6.54	\$32.70	\$7.85	\$15.70
Total			\$116.25		\$64.75	
Toro Workman 4300-D 4WD						
1	2	Element Oil Transmission Filter, 108-3842	\$7.03	\$7.03		
2	1	Air Filter, 108-3811	\$22.07	\$44.14		
3	2	Element Spin on Fuel Filter, 63-8300	\$41.78	\$125.34		
4	1	V Belt, 99-9156	\$13.16	\$52.64		
5	2	Filter Oil Transmission, 54 -0110	\$9.77	\$48.85		
Total			\$2,778.00		\$0.00	
Roro Procore 648 Aerator						
1	2	Cone-Bearing (w, scal) In. 107-7589				
2	2	Cup-Bearing, 107-7590				
3	1	Switch-Ignition, 83-0020	\$33.99	\$101.97		
4	4	Relay, 99-7430				
5	1	Belt, 3V, 105-0989				
6	1	Pulley-Idler, 99-3621				
7	1	Clutch-Electric, 108-2126				
8	1	Belt-Banded, 4 Groove, 105-0991				
9	1	V-Belt, 107-7513				
10	1	Pulley-Idler, 112426	\$13.99	\$139.90		
11	1	Hyd-Cyclasm, 105-1030				
Total			\$241.87		\$0.00	
Ryan-Trac Aire Aerator						
1	96	½" Coring Tine			\$5.55	\$532.80
2	96	¾" Coring Tine			\$6.18	\$593.28
Total			\$0.00		\$1,126.08	
Smithco Spray Star 2000 Sprayer						
1	1	Adapter, 16-961			\$8.20	\$8.20
2	1	Coupler, 16-962			\$22.74	\$22.74
3	2	Safety Filter, p822858	\$22.55	\$67.65	\$23.80	\$47.60
4	1	Air Cleaner, 500919	\$27.46	\$109.84	\$26.92	\$26.92
5	1	U-Belt, 30-137			\$23.25	\$23.25
6	1	Hypropump, 16-998			\$2,193.37	\$2,193.37
7	1	Manifold Valve, 15-743			\$1,122.95	\$1,122.95
8	1	50 Mesh Strainer, 16-968-03			\$34.75	\$34.75
9	1	EPDM Gasket, 14-521-02			\$8.02	\$8.02
10	1	10" Electric Hydra Actuator, 30-214			\$987.19	\$987.19
11	2	Hydraulic Oil filter, smi20-576-01			\$35.92	\$71.84
12	2	Air primary filter 50009190			\$26.92	\$53.84
13	3	Engine Oil filter 842921			\$11.05	\$33.15
14	3	Tee Jet Air Induction Spray Nozzle, ssaic11010vs			\$9.28	\$27.84
15	1	Tee Jet Nozzle body ssqj363c-3/4-nyb			\$9.82	\$9.82
16	1	Tee Jet Single hose barb for nozzle body smi18-417			\$4.40	\$4.40

Various Equipment Parts for The Golf Club of Florissant

17	1	Tee Jet Double hose barb for nozzle body smi18-416			\$5.17	\$5.17
18	1	Kyb lift actuator smi17-553			\$909.59	\$909.59
19	1	Rear wheel and tire mounted smi16-225			\$391.65	\$391.65
20	1	Front wheel and tire mounted smi16-857			\$236.35	\$236.35
Total				\$177.49		\$6,218.64
Toro Proforce Blower						
1	2	Element-Air Filter, KO24-083-03-S	\$17.84	\$35.68		
2	2	/D Oil Filter, KO12-050-01	\$13.22	\$26.44		
3	2	Filter- Oil. Hydraulic, 633750	\$10.24	\$20.48		
4	2	Filter-Oil. Hydraulic, 1079531	\$27.93	\$55.86		
Total				\$138.46		\$0.00
Turfco Blower						
1	1	Tire + Wheel Assembly, 669594			\$128.15	\$128.15
2	1	Oil Filter, 669772			\$17.30	\$17.30
3	1	Fuel Filter				
4	1	Air Filter p				
5	1	Air Filter s				
6	1	Fuse, 669406			\$0.36	\$0.36
7	1	Hand-Held Remote, 669870			\$285.72	\$285.72
8	1	Nozzle, 670278			\$105.43	\$105.43
Total				\$0.00		\$536.96
Jacobsen HR600 Wide Trim Roughmower						
1	1	Air Filter (Primary), 4133820	\$40.32	\$40.32	\$40.78	\$40.78
2	1	Air Filter (Secondary), 4133821	\$28.00	\$56.00	\$34.66	\$34.66
3	1	Water Separator, 4297126			\$104.07	\$104.07
4	1	Fuel Filter, 4297133			\$77.04	\$77.04
5	1	Hydro Filter, 4315387			\$91.09	\$91.09
6	1	Engine Oil Filter, 4113986	\$13.36	\$80.16	\$10.73	\$10.73
7	1	Fan Belt, 4297258			\$34.53	\$34.53
8	1	Hydro-Oil, 4361006			\$177.84	\$177.84
9	1	Rear Wheel and Tire, 4237069			\$563.42	\$563.42
10	1	Front Wheel and Tire, 4237069			\$563.42	\$563.42
11	3	Blade High Lift Gator (Front Deck), E4150198G			\$34.08	\$102.24
12	4	Blade High Lift Gator (Wing Deck) E4291662G			\$34.08	\$136.32
Total				\$176.48		\$1,936.14
Discount			2% 10, Net 20		"None"	
Delivery			1-2 Days ARO		30 Days From Date Order Placed	