

**City of Florissant
Water Slide Maintenance and Repair at Indoor Pool**

<i>Item</i>	<i>QTY</i>	<i>Description</i>	
			<i>Company</i>
			8 Blocks Maintenance dba SlidePros
			23321 MO 96 Oronago, MO 64855
#1	L.S.	Repair all Structural Repair in Ride Path Including Spider Cracks & Raised Edges	\$945.00
#2	L.S.	Re-caulk all Seams as Needed	\$475.00
#3	L.S.	Lay Non-Skid at Start Tub	\$475.00
#4	L.S.	Clean, Polish & Wax Entire Intererior of Slide	\$2,827.00
#5	L.S.	Bridge Repair	\$5,654.00
#6	L.S.	Slide & Stair Structure Repair	\$12,238.00
#7	L.S.	Wash Exterior of Slide with Cleaner	\$2,827.00
#8	L.S.	Prime Coat Bare Areas as Needed	\$945.00
TOTAL			\$26,386.00 *
#9		Federal Apprenticeship Policy	0%
		Cash Discount	0%
			* Note that prices for Bridge and Slide & Stair Structure can stand alone; all other prices do not stand alone and must be in addition to either the bridge and/or the Slide & Stair Structure Repair